

Abstract

A cutting tool 60 cuts along the butted portion between two members 10, 20. A filling material 30 is inserted to the gap 40 formed by said cutting, and a roller 70 presses protrusions 12 and 22 to crimp said protrusions 12 and 22 so as to fix said filling material to position. Next, friction stir welding is performed to the protrusions 12, 22 and the filling material 30 using a rotary tool 80. In another example, instead of cutting, the filling material can be welded and filled to the gap. In yet another example, cutting can be performed so as to approximate the two members before performing the friction stir welding step.

20084420 02443001